

## SSO Notification List

May 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/2/2021	1801 N Payson St	21217	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	927439
2	5/2/2021	2246 Eutaw Pl	21217	Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Determined house connection is damaged and needs repair.	Repair will restore line to regular functionality.	927457
3	5/3/2021	4313 W Forest Park Ave	21216	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the front cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results determined the lateral is now clear.	927569
4	5/3/2021	340 S Augusta Ave	21229	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed the lateral and mainline are both clear; CCTV inspection will be performed.	927632
5	5/3/2021	839 Ramsay St	21230	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection to confirm the line is now clear.	927704
6	5/3/2021	Lanier Ave & Cylburn Ave	21215	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now flowing freely; CCTV inspection will be performed.	927728
7	5/4/2021	5613 Gardenville Ave	21206	Rags	Dry	N/A	0	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results determined the lateral is now clear.	927982
8	5/7/2021	1848 W Baltimore St	21223	Rags, Grease, Trash	Dry	N/A	0	Gray water observed in the rear alley.	2	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed the mainline is now flowing freely. CCTV inspection will be performed.	928982
9	5/7/2021	6224 Everall Ave	21206	Rags, Roots	Dry	N/A	0	Heavy gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results determined the lateral is now clear.	929102
10	5/7/2021	513 N Belnord Ave	21205	Rags, Sand, Gravel, Rocks, Unknown	Dry	N/A	0	Gray water and rags observed around the cleanout.	1	Ran 6 ft of electric cable through the lateral; blockage remained.	Further investigation will take place, including CCTV inspection.	929115
11	5/10/2021	3703 Oakmont Ave	21215	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are now flowing freely. CCTV inspection will be performed.	930746
12	5/10/2021	812 N Streeper St	21205	Rags	Wet	N/A	0	Gray water and paper observed around the rear cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Dye testing was performed. CCTV inspection will take place in the future.	930782
13	5/10/2021	2781 Wilkens Ave	21223	Infiltration, Structural	Dry	Gwynns Falls	5880	Sewage discharging intermittently due to infiltration of storm along with changes in flow.	147,000	The bypass pump was throttled up to increase pumping speed and stop sewage.	Engineers are working on lining sewage pipe to prevent any future SSOs.	N/A
14	5/11/2021	E Fairmount Ave & N Washington St	21231	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole.	1	Relieved mainline choke with 50 ft of pressure hose.	Confirmed that the line is clear at this time; CCTV inspection will be performed.	930974
15	5/11/2021	2115 E Cold Spring Ln	21214	Rags, Unknown	Wet	N/A	0	Gray water and debris observed around the cleanout.	1	Ran 60 ft of electric cable through the lateral to remove obstructions.	Left notice for consumer to replace cleanout cap in order to perform a CCTV inspection.	931091
16	5/11/2021	4009 Chatham Rd	21207	Trash, Sand, Gravel, Rocks, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 12 ft of electric cable through the lateral; some blockage remained.	Further investigation is needed to ensure the line is clear.	931032
17	5/12/2021	2527 Ashton St	21223	Rags, Trash	Dry	Gwynns Falls	196	Gray water escaping the manhole in the rear alley.	196	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the mainline is now flowing freely. CCTV inspection will be performed.	931317
18	5/12/2021	4903 W Forest Park Ave	21216	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral is now clear.	931330
19	5/13/2021	409 N Belnord Ave	21224	Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 25 ft of electric cable.	CCTV inspection and lateral launch will be performed to ensure all obstructions were removed.	931362
20	5/14/2021	3000 Erdman Ave	21213	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and flushed the mainline.	931725
21	5/14/2021	515 E 38th St	21218	Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 15 ft of electric cable through the lateral; determined structural damage exists.	Line will be repaired and will be restored to regular functionality.	931825
22	5/15/2021	2716 Saint Paul St	21218	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results confirmed the lateral is clear at this time.	931937

## SSO Notification List

May 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
23	5/16/2021	2657 Norland Rd	21230	Rags, Sand, Gravel, Rocks	Dry	N/A	0	Gray water observed at the front of the property.	1	Ran 15 ft of electric cable through the lateral.	Confirmed the lateral is clear.	931991
24	5/17/2021	1801 N Payson St	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results confirmed the lateral is clear.	932160
25	5/17/2021	E Cold Spring Ln & York Rd	21212	Rags, Trash	Dry	Tiffany Run	78	Choked sanitary mainline causing wastewater to infiltrate the storm drain.	390	Relieved mainline choke with 280 ft of pressure hose.	CCTV inspection will be performed to ensure all obstructions were removed.	932098
26	5/17/2021	2157 Whistler Ave - (Private)	21230	Structural	Dry	N/A	0	Gray water observed at the front of the property.	(1)	Ran 4 ft of electric cable; determined lateral is damaged on consumer's side of pipe.	Informed consumer City's pipe is clear. They need to have private plumber address issue.	932136
27	5/18/2021	2919 Overland Ave	21214	Rags, Roots, Grease	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results determined the lateral and mainline are clear.	932279
28	5/18/2021	Key Hwy & E Cross St	21230	Structural	Dry	N/A	0	Gray water observed on the street.	5	Determined structural damage exists. Pipe will need repair.	Contractor has been assigned to complete repairs to the line.	932417
29	5/19/2021	5332 Nelson Ave	21215	Rags, Trash	Dry	N/A	0	Gray water and rags observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and results showed the lateral is now clear.	932640
30	5/19/2021	2510 Queen Anne Rd	21216	Structural	Dry	Gwynns Falls	1611	Wastewater leaking from house connection into storm drain.	16	Lateral was repaired to restore regular functionality and abate the overflow.	Dye testing was performed to confirm repair was effective and that sewage is no longer entering the storm drain.	932655
31	5/19/2021	434 S Augusta Ave	21229	Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear.	932854
32	5/20/2021	6434 O'Donnell St	21224	Rags, Grease	Dry	N/A	0	Gray water and paper observed around the manhole.	3	Relieved mainline choke with 150 ft of pressure hose.	Confirmed mainline is now flowing freely; CCTV inspection will be performed.	932933
33	5/20/2021	1525 Edmondson Ave	21223	Rags, Roots, Grease, Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 40 ft of electric cable.	CCTV inspection revealed minor structural damage to the lateral. Repairs will take place.	932977
34	5/22/2021	1512 W Lanvale St	21217	Sand, Gravel, Rocks, Structural	Dry	N/A	0	Gray water observed at the rear of the property.	2	Ran 17 of electric cable through the lateral; determined structural damage exists.	Line will be repaired to restore house connection to regular functionality.	933453
35	5/22/2021	789 Yale Ave	21229	Rags, Grease, Trash	Dry	Gwynns Falls	243	Gray water escaping the manhole at the rear of the property and entering nearby storm drain.	729	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is now flowing freely; CCTV inspection will be performed.	933466
36	5/22/2021	1222 Ashland Ave	21202	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results determined the lateral is clear.	933531
37	5/22/2021	1610 Elmtree St	21226	Structural	Dry	N/A	0	Gray water observed at the rear of the property.	2	Ran 2 ft of electric cable through the lateral; determined structural damage exists.	Pipe will be repaired to restore house connection to regular functionality.	933537
38	5/24/2021	4 Millbrook Rd	21218	Rags, Roots	Dry	N/A	0	Gray water observed near the front of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Flushed and cleaned the 8" mainline. Confirmed lines are clear.	934618
39	5/24/2021	2402 Barclay St	21218	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran electric cable through the lateral to relieve the choke.	Advised consumer to install a cleanout cap.	934767
40	5/25/2021	2803 N Loudon Ave	21216	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	This location has been placed on routine cleaning due to continued root intrusion.	935128
41	5/26/2021	2401 Frederick Ave	21223	Rags, Trash	Wet	Gwynns Falls	80	Gray water escaping a manhole in the street.	160	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed the mainline is now clear; CCTV inspection will be performed.	935410
42	5/27/2021	326 S Mount St	21223	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral is now clear.	935568
43	5/27/2021	4009 Barrington Rd	21207	Rags, Roots, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results showed the lateral is now clear.	935681
44	5/28/2021	2440 Cylburn Ave	21215	Rags, Trash	Wet	Jones Falls	175	Heavy gray water escaping the manhole.	875	Relieved mainline choke with 200 ft of pressure hose.	Confirmed the line is clear at this time. CCTV inspection will be performed.	935715

## SSO Notification List

May 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
45	5/28/2021	1701 Gwynns Falls Pkwy	21217	Sand, Gravel, Rocks, Structural	Wet	N/A	0	Gray water and debris observed at the rear of the property.	1	Ran 30 ft of electric cable through the lateral; determined blockage remains.	Further investigation, including a CCTV inspection, will take place to determine solution.	935860
46	5/28/2021	W Cold Spring Ln & Towanda Ave	21215	Rags, Rain, Trash	Wet	N/A	0	Gray water observed around the manhole in the street.	5	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear and flowing freely.	935887
47	5/29/2021	22 S Tremont Rd	21229	Rags, Roots	Wet	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the lateral is clear.	935892
				# WWO	13			TOTAL	149,424	UNDER 100 GALLONS	40	