

SSO Notification List

May 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	5/2/2016	1813 W. Lafayette Ave	21217	Trash, Sand, Gravel, Rocks, Pipe Break	WWO	N/A	Not Witnessed	Gray water and debris	Evidence of Overflow	Relieved house connection choke with 4 ft of electric machine	CCTV	303449
2	5/3/2016	2202 E Fairmont Ave	21231	Roots	DWO	N/A	Not Witnessed	Tissue and debris	Evidence of Overflow	Relieved house connection choke with electric machine and H-cutter	Line to be CCTV'd and recommended for root control	303722
3	5/5/2016	428 E Preston St	21202	Rags, Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	89	Sewer water and toilet paper overflowing	178	Relieved house connection choke with electric machine and pressure truck	CCTV	304045
4	5/6/2016	1804 Bolton St	21217	Rags, Roots	WWO	N/A	Not Witnessed	Debris and toilet paper around clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	304273
5	5/6/2016	2900 Rosalind Ave	21215	Rags, Grease	WWO	N/A	191	Grease, rags, and debris flowing from the manhole	1,910	Relieved mainline choke with 150 ft of pressure truck on 8" line	CCTV	304251
6	5/6/2016	5816 Berkley Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Gray water around clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	304158
7	5/6/2016	6221 Greenspring Ave	21209	Rags	WWO	N/A	694	Heavy gray water overflowing	694	Relieved house connection choke with 100 ft of electric machine on 6" line	CCTV	304134
8	5/9/2016	1318 Hull St	21230	Unknown	WWO	N/A	Not Witnessed	Evidence of overflow. Rear house connection choke	Evidence of Overflow	Ran 75 ft of electric machine to try and relieve house connection choke	Left plumbers notice to locate or install clean out	300421
9	5/9/2016	3007 Ridgewood Ave	21215	Rags, Roots	WWO	N/A	Not Witnessed	Paper and debris around the clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	304569
10	5/9/2016	3701 Southwestern Blvd	21229	Rags, Grease	WWO	N/A	184	Gray water overflowing	368	Pressure machine relieved mainline choke with 400 ft of pressure hose	CCTV	304611
11	5/9/2016	2951 Rosalind Ave	21215	Rags, Trash, Sand, Gravel, Rocks	WWO	Jones Falls	4,814	Sewage leaking from sanitary sewer pipe and discharging into adjacent storm drain pipe. Found during routine monitoring	4,814	Maintenance uncovered a buried manhole and was able to relieve the mainline choke that was the cause of this overflow. Mainline was flushed and cleared. Overflow is no longer active	CCTV	304571
12	5/10/2016	4522 Keswick Rd	21210	Rags, Pipe Break	WWO	N/A	Not Witnessed	Gray water and debris around the house connection	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	304744
13	5/10/2016	4705 Keswick Rd	21210	Roots	WWO	N/A	Not Witnessed	Gray water and evidence around clean out	Evidence of Overflow	Relieved choke with 100 ft of pressure machine hose with pressure truck	CCTV	304862
14	5/10/2016	Ravenwood Ave and Belair Rd	21213	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	113	Mainline choke, manhole overflowing	339	Relieved mainline choke with 300 ft of pressure truck on 8 inch line	CCTV	304737
15	5/11/2016	2910 Woodland Ave	21215	Infiltration/Inflow, Pipe Break	WWO	Jones Falls	39,069	Collapsed house connection causing discharge into storm drain pipe. Found from routine sampling	9,767	Ran 60 ft of electric machine cable to try and relieve choke, unable to pass. Maintenance performed repair on broken house connection	Construction repaired broken house connection, pipe no longer leaking	304977

SSO Notification List

May 2016

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
16	5/12/2016	302 Woodlawn Rd	21210	Rags, Roots, Grease	WWO	N/A	Not Witnessed	Gray debris and evidence	Evidence of Overflow	Relieved mainline choke with 300 ft of pressure truck on 6" line	CCTV	305241
17	5/12/2016	1052 Bethune Rd	21225	Rags, Roots, Trash, Sand, Gravel, Rocks	WWO	N/A	115	Heavy gray water	2,300	Relieved mainline choke with 400 ft of pressure truck on 15" line	CCTV	35164
18	5/12/2016	2904 Woodland Ave	21215	Infiltration/Inflow, Pipe Break	WWO	Jones Falls	299,457	Leaking house connection causing discharge into storm drain pipe. Found from OCAL routine sampling.	14,972	Damaged house connection was repaired	Contractor made repairs to damaged house connection	305339
19	5/12/2016	2912 Woodland Ave	21215	Infiltration/Inflow, Pipe Break	WWO	Jones Falls	19,917	Offset joints on house connection causing discharge into storm drain pipe. Found from routine sampling.	1,394	Repairs made to broken house connection, pipe no longer leaking	CCTV, Broken pipe was repaired. No longer leaking	305340
20	5/13/2016	2725 Hampden Ave	21211	Pipe Break	WWO	N/A	Not Witnessed	Debris and toilet paper	Evidence of Overflow	Ran 9' of electric machine to try and relieve choke	Bypass pumping initiated, refer for Construction for repairs	305329
21	5/14/2016	104 Elmhurst Ave	21210	Rags, Roots	WWO	N/A	Not Witnessed	Heavy gray water and evidence visible around the clean out	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine on 6" line	CCTV	305466
22	5/14/2016	6003 Pinehurst Rd	21212	Rags, Roots	WWO	N/A	Not Witnessed	Toilet paper and debris visible around the clean out	Evidence of Overflow	Relieved house connection choke with 15 ft of electric machine on 6" line	CCTV	305430
23	5/18/2016	1821 W Mulberry St	21223	Rags, Roots	WWO	N/A	Not Witnessed	Gray debris in yard	Evidence of Overflow	Relieved house connection choke with 40 ft of electric machine on 6" line	CCTV	305989
24	5/18/2016	2019 Barclay St	21218	Rags, Grease	WWO	N/A	Not Witnessed	Light paper, grease	Evidence of Overflow	Cleaned line with 45 ft of electric machine	CCTV	306042
25	5/18/2016	2024 Smallwood St	21216	Pipe Break	WWO	N/A	Not Witnessed	Paper and debris	Evidence of Overflow	B.G.E to remove pole off broken lateral, refer for construction for repairs	CCTV	306009
26	5/19/2016	1707 Warwick Ave	21216	Grease, Trash, Sand, Gravel, Rocks	WWO	N/A	188	Grease and debris overflowing	940	Pressure truck relieved mainline choke, used 300 ft of pressure machine hose	CCTV	306225
27	5/19/2016	2417 Madison Ave	21217	Rags, Roots	WWO	N/A	Not Witnessed	Found evidence of overflow in rear of location	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	306174
28	5/20/2016	1621 N Chapel St	21213	Rags, Trash, Sand, Gravel, Rocks	DWO	N/A	64	Toilet paper and murky water overflowing	128	Relieved house connection choke with 30 ft of electric machine on 6 in line	CCTV	306378
29	5/20/2016	2418 Saint Paul St	21218	Roots	DWO	N/A	Not Witnessed	Toilet paper and evidence around house connection	Evidence of Overflow	Relieved house connection choke with 45 ft of electric machine	CCTV	306309
30	5/20/2016	3000 Harford Rd	21218	Rags, Roots, Grease	DWO	N/A	90	Manhole overflowing gray colored water	450	Relieved mainline choke with 175 ft of pressure truck on 6 in line	CCTV	306390
31	5/20/2016	4307 Laplata Ave	21211	Rags, Grease, Trash, Sand, Gravel, Rocks	DWO	Jones Falls	70	Cloudy overflowing water	350	Used pressure truck to flush and relieve mainline choke, used 175 ft of pressure hose	CCTV	306313

