

## SSO Notification List

April 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2021	1933 McCulloh St	21217	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Ran 30 ft of electric cable through the lateral, then flushed the mainline with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed on the lateral.	921901
2	4/1/2021	2 N Bentalou St	21223	Rags	Wet	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and determined the line is clear.	921929
3	4/1/2021	1412 N Luzerne Ave	21213	Trash	Wet	N/A	0	Gray water and debris observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear.	921931
4	4/1/2021	614 Hollen Rd	21212	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the rear cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the lateral to be clear.	921962
5	4/3/2021	5007 Greenhill Ave	21206	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection and lateral cleaning will be performed.	922172
6	4/4/2021	Leith Walk & E Northern Pkwy	21239	Rags, Trash	Dry	N/A	98	Gray water escaping the manhole in the street.	49	Relieved mainline choke with 200 ft of pressure hose.	Mainline CCTV inspection will be performed to ensure the line is clear.	922224
7	4/4/2021	931 Wilmington Ave	21223	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	2	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to confirm all obstructions were removed.	922220
8	4/5/2021	2423 Perring Manor Rd	21234	Rags, Roots, Grease, Trash	Dry	N/A	0	Heavy gray water observed on the sidewalk.	3	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection and mainline cleaning will be performed on pipe.	922490
9	4/6/2021	4104 E Northern Pkwy	21206	Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and determined the lateral and mainlines are clear.	922591
10	4/6/2021	609 Linnard St	21229	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is now clear and that obstructions were removed.	922741
11	4/7/2021	2433 Maryland Ave	21218	Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral and mainline are clear.	922808
12	4/7/2021	2 N Bentalou St	21223	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral is clear.	922954
13	4/7/2021	1611 Laurens St	21217	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed a CCTV inspection and determined the lateral and mainline are clear.	922862
14	4/8/2021	3224 Lyndale Ave	21213	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral is now clear.	923240
15	4/8/2021	1600 E Fairmount Ave	21231	Rags, Grease, Trash	Dry	N/A	0	Gray water observed around the manhole in the street.	2	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection and vac-con will be used to confirm all obstructions were removed.	923195
16	4/9/2021	700 Cumberland St	21217	Roots, Trash	Wet	N/A	0	Gray water and paper observed surrounding the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed the lateral is clear and the mainline is flowing freely.	923337
17	4/10/2021	2754 Kinsey Ave	21223	Structural	Wet	N/A	0	Gray water observed around the cleanout.	1	Lateral will need to be repaired. Bypass pumping will be required during construction.	Repairs will restore line to regular functionality.	923455
18	4/11/2021	3404 Pinkney Rd	21215	Rags, Grease	Wet	Jones Falls	0	Gray water observed in the rear alley near manhole and storm drain.	10	Relieved mainline choke with 250 ft of pressure hose.	Performed CCTV inspection and put line on routine cleaning due to size.	923478
19	4/12/2021	1613 N Warwick Ave	21216	Rags, Trash, Other	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft electric cable.	Performed CCTV inspection; confirmed lateral is clear at this time. left pamphlet and door notice to that effect.	923540
20	4/12/2021	2223 Essex St	21231	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed; flushed and cleaned the 8" mainline.	923620

## SSO Notification List

April 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
21	4/13/2021	2600 N Longwood St	21216	Rags, Roots, Grease	Wet	Gwynns Falls	123	Surcharging manhole flowing into adjacent storm inlet.	2,460	Relieved 8" mainline choke with 250 ft of pressure hose.	Confirmed the mainline is flowing freely at this time; CCTV inspection will be performed.	923796
22	4/15/2021	105 Deepdene Rd	21210	Rags, Roots, Trash	Wet	N/A	0	Gray water observed around the manhole.	2	Relieved 6" mainline choke with 100 ft of pressure hose.	Mainline is under project design phase for replacement. Construction to begin in 2022.	924507
23	4/15/2021	3502 The Alameda	21218	Rags, Trash	Wet	N/A	0	Gray water observed around the manhole.	2	Relieved mainline choke with 300 ft of pressure hose.	Confirmed the mainline is flowing freely; CCTV inspection will be performed.	924541
24	4/17/2021	2419 S Paca St	21230	Unknown	Wet	N/A	0	Gray water observed around the cleanout.	1	Arrived to location and determined the lateral is not able to be accessed at this time.	Advised consumer to have plumber install proper cleanout so that work can be performed.	924871
25	4/18/2021	310 S Catherine St	21223	Structural	Dry	N/A	2445	Gray water escaping the manhole.	2,445	Repaired broken sanitary sewer mainline to return flow to normal and stop the overflow.	Follow-up work will be performed to remove unnecessary material, including cement.	923910
26	4/19/2021	456 Roundview Rd	21225	Roots	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed a CCTV inspection and results confirmed the line is now clear.	925369
27	4/20/2021	825 Yale Ave - (Private)	21229	Rags, Grease, Trash	Dry	Gwynns Falls	74	Gray water escaping a private manhole.	(370)	DPW assisted by relieving mainline choke with pressure hose.	Confirmed private line is clear.	925247
28	4/20/2021	4403 Frederick Ave	21229	Rags, Grease, Trash	Dry	Gwynns Falls	94	Gray water escaping the manhole.	470	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is flowing freely at this time. CCTV inspection will be performed.	925261
29	4/20/2021	5115 Norwood Rd	21212	Rags, Roots, Grease	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and results showed the line is clear.	925269
30	4/20/2021	329 E 22nd St	21218	Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 95 ft of electric cable.	Confirmed that the lateral is now clear of obstructions.	925339
31	4/21/2021	2565 W Fairmount Ave	21223	Rags, Roots	Dry	N/A	0	Heavy gray water and rags observed around the cleanout.	1	Relieved connection choke using 30 ft of electric cable.	Location has been placed on routine cleaning to reduce SSO likelihood.	925635
32	4/23/2021	2554 Arunah Ave	21216	Trash, Sand, Gravel, Rocks	Dry	N/A	0	Gray water and debris observed at the front of the property.	2	Relieved connection choke using 45 ft of electric cable and various cutters.	Performed CCTV inspection; confirmed lateral is clear at this time.	926215
33	4/23/2021	700 Cumberland St	21217	Rags, Trash	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed that there are no longer obstructions in the lateral.	926337
34	4/24/2021	2157 Whistler Ave	21230	Rags, Roots, Trash	Dry	N/A	0	Gray water and paper observed on the sidewalk.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and determined the lateral and mainline are clear.	926349
35	4/24/2021	1452 Redfern Ave	21211	Rags, Roots, Trash	Dry	N/A	46	Gray water discharging from sump pump.	46	Relieved mainline choke with 250 ft of pressure hose.	Confirmed the mainline is now flowing freely at this time. CCTV inspection will be performed.	926364
36	4/26/2021	4215 Liberty Heights Ave	21207	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 75 ft of electric cable.	CCTV inspection performed. This location will be placed on routine cleaning/root control.	926439
37	4/26/2021	1214 Homewood Ave	21202	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and results showed the line to be clear.	926559
38	4/26/2021	614 Venable Ave	21218	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and results showed the line to be clear.	926611
39	4/27/2021	1525 Edmondson Ave	21223	Trash	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear at this time. Advised resident to replace cleanout cap.	926676
40	4/29/2021	4016 Fairfax Rd	21216	Rags, Infiltration, Trash	Dry	Gwynns Falls	97	Gray water escaping the mainline and entering nearby storm drain.	1,455	Relieved mainline choke with 100 ft of pressure hose.	Water quality sampling and CCTV inspection will be performed at this location.	927139

## SSO Notification List

April 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
41	4/29/2021	3436 Dudley Ave	21213	Grease, Trash	Dry	N/A	0	Gray water escaping sump pump.	3	Flushed the mainline with pressure hose to relieve the choke.	CCTV inspection will be performed to further determine a cause.	926603
42	4/30/2021	6714 Holabird Ave	21222	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and determined the lateral and mainline are clear.	927252
43	4/30/2021	2315 McCulloh St	21217	Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed the lateral is now clear. CCTV inspection will be performed.	927345
				# WWO	18			TOTAL	6,984	UNDER 100 GALLONS	38	