

SSO Notification List

December 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	12/1/2019	3700 Tudor Arms Ave	21211	Rags, Grease, Structural	Wet	N/A	1556	Overflowing manhole in pond.	194,500	Flushed the line and set up bypass pumping to stop the overflow. Placed warning signage in the nearby area.	City is exploring long-term solution to make repairs to the line. Bypass should prevent overflows.	810768
2	12/4/2019	Cyburn Ave & Greenspring Ave	21209	Rags, Roots, Grease	Wet	Jones Falls	63	Overflowing manhole in the street.	3,150	Relieved mainline choke with 300 ft. of pressure hose.	Confirmed mainline is clear.	811738
3	12/4/2019	2401 Frederick Ave	21223	Rags, Grease	Dry	N/A	0	Gray water and debris observed at the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed line is clear. Advised consumer to replace cleanout cap.	812245
4	12/5/2019	1245 Walker Ave	21239	Rags	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	4	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	812562
5	12/5/2019	3703 Frankford Ave	21206	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout and alley.	10	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	812582
6	12/7/2019	Cresmont Ave & W 29th St	21211	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the manhole on the sidewalk.	8	Relieved mainline choke with 250 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	813060
7	12/7/2019	11 Gorman Ave	21223	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear; CCTV inspection will be performed.	813047
8	12/8/2019	3700 Tudor Arms Ave	21211	Structural	Dry	N/A	930	Pump malfunction caused sewage to escape the manhole.	46,500	Bypass pump was repaired to contain overflow.	Bypass pump will control flow until repairs to mainline are made.	813323
9	12/9/2019	1735 Guilford Ave	21202	Rags	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	6	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	813951
10	12/10/2019	3700 Tudor Arms Ave	21211	Structural	Wet	N/A	60	Manhole overflowing into nearby pond.	7,500	A new pump was set up to accommodate the flow. Contractor is on-site to maintain pump.	Long-term solution for repair is being investigated and will eventually return flow to regular operations.	
11	12/12/2019	1731 Ruxton Ave	21216	Rags, Trash	Wet	N/A	0	Water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Confirmed line is clear.	814869
12	12/12/2019	6007 Falls Rd	21210	Rags, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	2	Ran 75 ft of electric cable through lateral. Mainline will be flushed and cleaned.	CCTV inspection will be performed.	815359
13	12/12/2019	18 Merrymount Rd	21210	Rags, Grease, Trash	Wet	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	10	Ran 75 ft of electric cable and flushed the mainline to relieve house connection choke.	Performed CCTV inspection; confirmed lateral and mainline are clear.	814839
14	12/14/2019	2928 Baker St	21216	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	815854
15	12/15/2019	810 N Hilton St	21229	Rags, Trash	Wet	Gwynns Falls	375	Gray water escaping the manhole.	375	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed.	815964
16	12/17/2019	Harford Rd & Sylvan Ave	21214	Rags, Grease, Trash	Wet	N/A	216	Gray water escaping the manhole in the street.	1,080	Relieved 8" mainline choke with 350 ft of pressure hose.	Confirmed mainline is clear.	816964
17	12/18/2019	837 W Lombard St	21201	Roots, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	817365
18	12/19/2019	4031 Fairview Ave	21216	Rags, Grease, Trash	Wet	Gwynns Falls	81	Sewage infiltration observed during routine monitoring of outfall.	2,430	Relieved 8" mainline choke with 50 ft of pressure hose.	Confirmed mainline is clear.	817529
19	12/20/2019	2201 Rogene Dr	21209	Rags, Roots, Grease, Trash, Other	Dry	N/A	1536	Heavy gray water discharging from sanitary stack.	230,400	Contractor engaged to perform cleaning and abate the SSO by removing lining, the main cause of the blockage.	CCTV inspection will be performed; bypass pump may be set up to accomplish this task.	817763

SSO Notification List

December 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	12/20/2019	213 Edgevale Rd	21210	Roots	Dry	N/A	0	Water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed.	817802
21	12/20/2019	769 N Edgewood St	21229	Rags, Roots, Grease, Trash	Dry	Gwynns Falls	548	Sewage escaping the manhole in the street.	2,740	Relieved mainline choke with 220 ft of pressure hose. Salted the area to prevent ice buildup.	CCTV inspection will be performed.	818069
22	12/21/2019	4217 Primrose Ave	21215	Rags, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved choke using 60 ft of electric cable in the lateral and flushed the mainline with 300 ft of pressure hose.	Confirmed mainline and house connection are clear; CCTV inspection will be performed.	818135
23	12/24/2019	436 Kane St	21224	Rags, Grease, Trash	Dry	N/A	97	Gray water escaping the manhole.	970	Relieved 8" mainline choke with 85 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	819551
24	12/24/2019	1211 W Northern Pkwy	21209	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection.	819695
25	12/24/2019	4309 Groveland Ave	21215	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable; flushed and cleaned the 8" mainline.	Performed CCTV inspection; confirmed mainline and lateral are clear.	819711
26	12/25/2019	3915 Liberty Heights Ave	21207	Rags	Dry	N/A	0	Gray water observed around the cleanout.	25	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear.	819722
27	12/25/2019	1807 Bolton St	21217	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	8	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	819746
28	12/26/2019	2642 Harford Rd	21218	Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection.	820027
29	12/27/2019	2406 E Fairmount Ave	21224	Trash, Other	Dry	N/A	0	Gray water observed around the cleanout on the sidewalk.	8	Ran 10 ft of electric cable through house connection.	CCTV inspection will be performed to further investigate possible blockage.	820180
30	12/27/2019	4109 Massachusetts Ave	21229	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	820204
31	12/28/2019	817 N Bentalou St	21216	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout and sidewalk.	5	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	820445
32	12/28/2019	4213 Audrey Ave	21225	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear.	820582
33	12/28/2019	802 Saint Dunstons Rd	21212	Rags, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	820597
34	12/29/2019	3814 White Ave	21206	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed.	820666
				# WWO	13			TOTAL	489,777	UNDER 100 GALLONS	24	