

SSO Notification List

February 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	2/3/2021	3330 Reisterstown Rd	21215	Rags, Grease	Wet	Gwynns Falls	158	Gray water escaping the manhole.	2,370	Relieved mainline choke with 250 ft of pressure hose.	CCTV inspection will be performed.	907362
2	2/3/2021	2642 Harford Rd	21218	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	907380
3	2/6/2021	1139 Steelton Ave	21224	Trash, Unknown	Wet	N/A	0	Gray water and debris observed around the cleanout.	3	Unable to relieve choke; bypass pumping will be initiated.	Further investigation will take place.	907913
4	2/6/2021	1621 N Rosedale St	21216	Rags, Trash	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved choke with 11 ft of electric cable and 150 ft of pressure hose.	Confirmed line is clear.	907941
5	2/6/2021	4600 Hampnett Ave	21214	Rags, Roots	Wet	N/A	0	Heavy gray water and paper observed around the cleanout.	5	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection.	907948
6	2/7/2021	6831 Harford Rd	21234	Trash, Sand, Gravel, Rocks	Wet	N/A	0	Gray water observed around the cleanout.	2	Relieved mainline choke with pressure hose.	Confirmed line is clear.	908322
7	2/8/2021	5302 Elsrode Ave	21214	Rags, Trash	Wet	Herring Run	186	Gray water escaping the mainline.	372	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	908369
8	2/8/2021	Hickory Ave & W 41st St	21211	Rags, Grease	Wet	Jones Falls	212	Heavy gray water escaping the manhole.	1,060	Relieved mainline choke with 75 ft of pressure hose.	Confirmed mainline is clear.	908346
9	2/8/2021	2014 Brunt St	21217	Unknown	Wet	N/A	0	Gray water observed at the rear of the property.	2	Access issue prevented maintenance crew from performing necessary work.	Consumer will call back and grant access to property.	908538
10	2/9/2021	5013 Greenhill Ave	21206	Rags	Wet	N/A	0	Gray water observed at the front of the property.	2	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed in the future.	908600
11	2/9/2021	535 Benninghaus Rd	21212	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed to confirm line is clear.	908624
12	2/9/2021	1222 Ashland Ave	21202	Rags, Trash	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and determined the line is clear.	908700
13	2/9/2021	603 S Glover St	21224	Rags, Grease	Wet	N/A	0	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with electric cable.	CCTV inspection will be performed to determine that the line is flowing freely.	908744
14	2/10/2021	3214 Belair Rd	21213	Rags, Grease, Trash	Wet	Herring Run	414	Mainline choke causing subsurface overflow.	2,070	Relieved mainline choke with 300 ft of pressure hose.	A CCTV inspection will be performed in the future to determine if all obstructions were removed from the pipe.	908919
15	2/10/2021	4809 Erdman Ave	21205	Rags, Grease, Trash	Wet	Herring Run	808	Gray water escaping the cleanout.	808	Relieved choke with 150 ft of electric cable and 300 ft of pressure hose.	Confirmed the lateral is clear and the mainline is flowing freely. A CCTV inspection will be performed.	908880
16	2/11/2021	3404 Glen Ave - SSO Site #155	21215	Trash, Sand, Gravel, Rocks	Dry	Jones Falls	16938	A structured overflow pipe is overflowing due to a restriction.	2,541	Debris was vacuumed out of manhole and downstream mainline was jetted and cleaned.	CCTV inspection was performed and video confirmed downstream sections are clear.	
17	2/12/2021	6701 Quad Ave	21237	Rags, Grease	Dry	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	CCTV inspection was performed; confirmed the lateral and mainline are clear.	909924
18	2/12/2021	1619 Gwynns Falls Pkwy	21217	Rags, Grease	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed to determine if all blockage was removed from the lateral.	909927
19	2/14/2021	2119 Kentucky Ave	21218	Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and confirmed blockage was removed from the lateral.	910047

SSO Notification List

February 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	2/15/2021	138 S Loudon Ave	21229	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection revealed inconclusive footage. Mainline will be cleaned.	910070
21	2/15/2021	644 E Clement St	21230	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed to confirm the lateral is clear.	910087
22	2/16/2021	428 E Preston St	21202	Unknown	Wet	N/A	1830	Gray water escaping the manhole and entering nearby Amtrak railway.	3,660	Contractor set up bypass pumping to divert flow and abate the overflow.	Further investigation will take place to determine the cause and return pipe to regular functionality.	
23	2/16/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	50	Manhole adjacent to creek overflowed due to heavy rain.	49,000	Overflow subsided following heavy rain event.	Capital improvement projects are under design to prevent future overflows.	
24	2/16/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	90	Structure monitored by metering equipment in the pipe. Not visually observed.	26,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
25	2/16/2021	119 E Fort Ave	21230	Rags, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection and results confirmed that the pipe is clear.	910303
26	2/17/2021	1214 Homewood Ave	21202	Trash	Wet	N/A	0	Gray water and paper observed at the rear of the property.	6	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection and revealed the line is now clear.	910421
27	2/17/2021	3379 Saint Benedict St	21229	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection and results confirmed the lateral is now clear.	910629
28	2/17/2021	5022 Denview Way	21206	Trash	Wet	N/A	0	Gray water observed in the area surrounding the manhole.	10	Relieved mainline choke with pressure hose.	CCTV inspection will be performed to confirm that the line is clear.	910456
29	2/17/2021	5622 Frankford Ave	21206	Structural	Wet	N/A	0	Toilet paper and sewage around base of clean out	10	Investigated location and determined structural damage exists in the lateral.	Pipe will be repaired. Bypass pumping will be initiated to provide relief until regular functionality is restored.	908433
30	2/21/2021	644 E Clement St	21230	Rags, Roots	Wet	N/A	0	Sewage and paper observed around the base of the cleanout.	2	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed, and mainline will be flushed.	911952
31	2/22/2021	412 George St	21201	Structural, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the side of the property.	1	Ran 9 ft of electric cable through the lateral; blockage remained.	Further investigation, including a CCTV inspection, will determine the cause of the issue.	912116
32	2/23/2021	6527 Parnell Ave	21222	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole in the street.	10	Relieved mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to determine if blockage was fully removed from the pipe.	912547
33	2/23/2021	2401 Allendale Rd	21216	Rags, Roots, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection and confirmed the lateral is clear.	912632
34	2/23/2021	1229 Greenmont Ave	21202	Rags, Trash	Wet	N/A	480	Gray water escaping the cleanout at the rear of the property.	240	Relieved house connection choke with 30 ft of electric cable.	CCTV inspection will be performed to ensure line is clear.	912649
35	2/23/2021	Fairview Ave & Oakfield Ave	21216	Rags, Trash	Wet	Gwynns Falls	434	Gray water escaping the manhole in the street.	868	Relieved mainline choke with 200 ft of pressure hose.	CCTV inspection will be performed to ensure mainline is now flowing freely.	912694
36	2/24/2021	501 N Rock Glen Rd	21229	Trash, Sand, Gravel, Rocks, Unknown	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Ran 45 ft of electric cable through the lateral.	Advised consumer to have contractor evaluate the cleanout they installed.	912789
37	2/24/2021	1251 N Broadway	21213	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed to ensure all obstructions were removed.	912870
38	2/26/2021	3700 Eastwood Dr	21206	Infiltration, Structural	Dry	Herring Run	TBD	Wastewater leaking from manhole and infiltrating the adjacent storm drain.	Ongoing - (0.5 gal/min)	Repair work will need to be done to restore manhole and line to regular functionality.	Once repair is completed, leak will stop and ideal flow will resume.	913636

SSO Notification List

February 2021

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
39	2/26/2021	2200 Cecil Ave	21218	Sand, Gravel, Rocks, Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 35 ft of electric cable through the lateral; blockage remained.	Further investigation will take place to determine cause of choke. Flushed and cleaned the mainline.	913720
40	2/26/2021	2610 Oswego Ave	21215	Roots, Grease	Dry	N/A	165	Gray water escaping the cleanout at the rear of the property.	83	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	914150
41	2/26/2021	2246 Eutaw Pl	21217	Structural, Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Ran 30 ft of electric cable through the lateral; determined structural damage exists.	Lateral will be repaired. Bypass pumping may be required during this timeframe.	913692
42	2/27/2021	1524 Pentwood Rd	21239	Rags, Roots, Grease, Trash	Wet	Herring Run	36	Gray water escaping the manhole in the street.	36	Relieved mainline choke with 275 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	914230
43	2/28/2021	3511 Greenspring Ave	21209	Unknown	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Line will be pumped down while further investigation takes place to determine a cause.	CCTV and other procedures will take place to restore line to regular functionality.	914297
44	2/28/2021	2829 Overland Ave	21214	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed in the future.	914321
45	2/28/2021	2440 Cylburn Ave	21215	Rags, Grease, Trash	Wet	Jones Falls	144	Heavy gray water escaping the manhole in the street.	7,200	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed in the future.	914319
46	2/28/2021	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	155	Structure monitored by metering equipment in the pipe. Not visually observed.	111,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of capital improvement projects.	
47	2/28/2021	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	510	Structure monitored by metering equipment in the pipe. Not visually observed.	1,492,000	SSO structure; not applicable.	SSO structure will be closed upon completion of necessary capital project.	
48	2/28/2021	3900 Belair Rd	21206	Rain	Wet	Herring Run	120	Manhole adjacent to creek overflowed due to heavy rain.	246,000	Overflow subsided following heavy rain event.	Capital improvement projects are under design to prevent future overflows.	
				# WWO	40			TOTAL	1,945,385	UNDER 100 GALLONS	32	