

## SSO Notification List

July 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	7/1/2020	3224 Fallstaff Rd	21208	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	870344
2	7/1/2020	3200 Piedmont Ave	21216	Rags, Infiltration, Trash	Wet	Gwynns Falls	113	Choked mainline causing subsurface sewage discharge into nearby storm drain.	339	Relieved mainline choke with 600 ft of pressure hose.	CCTV inspection will be performed.	870454
3	7/3/2020	1248 N Gay St	21213	Rags, Roots	Wet	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	870740
4	7/4/2020	4314 Wentworth Rd	21207	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	870790
5	7/4/2020	726 Newington Ave	21217	Trash	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed lateral is clear; mainline will be cleaned.	870810
6	7/8/2020	2913 Oakley Ave	21215	Rags	Wet	N/A	50	Gray water escaping the cleanout at the front of the property.	50	Relieved house connection choke with 30 ft of electric cable; cleaned the mainline.	Performed CCTV inspection; confirmed lateral is clear.	871361
7	7/8/2020	5226 Kelway Ave	21239	Rags, Trash	Wet	Chinquapin Run	151	Mainline choke causing subsurface overflow.	151	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	871366
8	7/11/2020	6413 Rosemont Ave	21206	Trash	Wet	N/A	0	Gray water observed around the cleanout.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed line is clear; lateral CCTV inspection will be performed.	871825
9	7/11/2020	6100 O'Donnell St	21224	Rags, Trash	Wet	Inner Harbor	0	Gray water observed around the manhole.	8	Relieved mainline choke with 225 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	871875
10	7/13/2020	1301 Woodbourne Ave	21239	Infiltration, Other	Wet	Chinquapin Run	1686	Abandoned sanitary sewer mainline discharging into stream from ground, confirmed with dye test.	84,300	Installed a bypass pump to abate the overflow.	Lines are currently under construction and will be replaced.	
11	7/15/2020	4029 Fairview Ave	21216	Rags, Roots, Grease	Wet	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	872409
12	7/15/2020	506 S Central Ave	21231	Rags, Grease, Trash	Wet	Inner Harbor	1174	Choked sanitary sewer overflowing into adjacent storm drain pipe.	587	Relieved choke by flushing the mainline with 350 ft of pressure hose.	CCTV inspection will be performed; confirmed sewage is no longer reaching the storm drain.	872415
13	7/16/2020	1100 E Belvedere Ave	21239	Rags, Trash	Dry	N/A	40	Gray water escaping the manhole.	280	Relieved mainline choke with 150 ft of pressure hose.	CCTV inspection will be performed.	872794
14	7/20/2020	5437 Springlake Way	21212	Rags, Trash	Dry	N/A	0	Gray water observed around sump pump at the front of the property.	20	Relieved mainline choke with 200 ft of pressure hose.	Mainline CCTV inspection will be performed.	873236
15	7/20/2020	33 W Talbott St	21225	Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Lateral CCTV inspection will be performed; mainline will be cleaned.	873358
16	7/21/2020	200 Deepdene Rd	21210	Rags, Grease	Dry	Jones Falls	0	Gray water observed around the manhole and stream.	10	Relieved mainline choke with 300 ft of pressure hose.	Confirmed line is clear.	872638
17	7/22/2020	1901 Falls Rd	21211	Rain	Wet	Jones Falls	50	Heavy gray water escaping the manhole.	5,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	873864
18	7/22/2020	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	45	Structure monitored by metering equipment in pipe. Not visually observed.	143,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
19	7/22/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	35	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe.	86,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
20	7/22/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	105	Structure monitored by metering equipment in pipe.	264,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
21	7/22/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	205	Structure monitored by metering equipment in pipe. Not visually observed.	504,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	

## SSO Notification List

July 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	7/22/2020	N Charles St & Lafayette Ave - SSO Site #154	21202	Rain	Wet	Jones Falls	30	SSO structure; not applicable.	26,000	Structure monitored by metering equipment in pipe; not applicable.	The SSO structure will be closed upon completion of necessary capital projects.	
23	7/22/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	90	Manhole adjacent to creek overflowed due to heavy rain.	865,000	Overflow subsided following heavy rain event.	Capital improvement projects have been implemented to prevent this location from overflowing.	
24	7/24/2020	5318 Norwood Ave	21207	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	874353
25	7/24/2020	E 32nd St & St Paul St - SSO Site #157	21218	Rain	Wet	Jones Falls	25	Structure monitored by metering equipment in pipe. Not visually observed.	4,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
26	7/24/2020	N Charles St & W Lanvale St - SSO Site #152	21202	Rain	Wet	Jones Falls	80	Structure discharges to a storm drain pipe and is monitored by metering equipment in the pipe.	91,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
27	7/24/2020	1901 Falls Rd - SSO Site #67	21211	Rain	Wet	Jones Falls	130	Structure discharges to a storm drain and is monitored by metering equipment in the pipe.	230,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
28	7/24/2020	428 E Preston St - SSO Site #72	21202	Rain	Wet	Jones Falls	230	SSO structure is monitored by metering equipment in the pipe.	1,570,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
29	7/24/2020	N Charles St & Lafayette Ave - SSO Site #154	21202	Rain	Wet	Jones Falls	35	Structure monitored by metering equipment in pipe. Not visually observed.	46,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
30	7/24/2020	Charing Cross Rd & Greenwich Ave - SSO Site #156	21229	Rain	Wet	Maidens Choice	15	Structure monitored by metering equipment in pipe. Not visually observed.	281	SSO structure; not applicable	Structure will be closed upon completion of necessary capital improvement project.	
31	7/24/2020	2121 Wicomico St	21230	Rain	Wet	Gwynns Falls	95	Gray water escaping the manhole. Confirmed via metering equipment.	124,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	874377
32	7/24/2020	1731 E Chase St	21205	Rain	Wet	Inner Harbor	50	Manhole surcharging due to heavy rain. Confirmed via metering equipment.	41,800	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	874359
33	7/24/2020	1800 E Eager St	21205	Rain	Wet	Inner Harbor	10	Gray water escaping the manhole. Confirmed via metering equipment.	50,000	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	874360
34	7/24/2020	3900 Belair Rd	21206	Rain	Wet	Herring Run	15	Manhole adjacent to creek overflowed due to heavy rain.	144,000	Overflow subsided following heavy rain event.	SSO will be prevented from reoccurring once capital improvement projects are completed.	
35	7/26/2020	3214 Piedmont Ave	21216	Rags, Trash, Structural	Wet	Gwynns Falls	93	Gray water escaping the mainline.	9,300	Relieved the mainline choke with 300 ft of pressure hose.	CCTV inspection will be performed to investigate potential structural damage to line.	874490
36	7/26/2020	305 E Lanvale St	21202	Rags, Trash	Wet	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	874519
37	7/28/2020	5714 Seymour Ave	21206	Rags, Roots, Trash	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	5	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	874881
38	7/29/2020	1808 Fairbank Rd	21209	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	875103
39	7/29/2020	5811 Pimlico Rd	21209	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout.	5	Relieved house connection choke with 100 ft of pressure hose.	CCTV inspection will be performed for the lateral and mainline.	875136
40	7/30/2020	1820 McCulloh St	21217	Unknown	Dry	N/A	0	Light gray water observed at the rear of the property.	1	Access issue prevented Maintenance crew from directly addressing the problem at this time.	Left notice for the owner to clear bushes around the cleanout and allow gate entry.	875351
				# WWO	30			TOTAL	4,289,151	UNDER 100 GALLONS	17	