

SSO Notification List

June 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	6/1/2020	261 W 31st St	21211	Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	3	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; mainline will be cleaned.	865109
2	6/2/2020	4118 Fernhill Ave	21215	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection.	865434
3	6/4/2020	4309 Springdale Ave	21207	Rags, Roots	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	10	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear.	865659
4	6/4/2020	209 Goodwood Grdns	21210	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the front of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	866077
5	6/4/2020	4029 Rogers Ave	21215	Trash, Structural	Dry	N/A	0	Gray water observed around the cleanout at the side of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Lateral had physically shifted, causing structural issue; pipe will be repaired.	866082
6	6/6/2020	1902 Dixon Rd - (Private)	21209	Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	866326
7	6/8/2020	3700 Springdale Ave	21216	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral and mainline are clear.	866590
8	6/11/2020	1932 McCulloh St	21217	Rags, Trash	Wet	N/A	0	Gray water and paper observed at the rear of the property.	2	Relieved house connection choke with 75 ft of electric cable.	Confirmed lateral and mainline are clear.	867202
9	6/14/2020	3309 Springdale Ave - (Private)	21216	Sand, Gravel, Rocks, Structural	Dry	N/A	0	Gray water observed around the cleanout at the front of the property.	2	Ran 45 ft of electric cable through lateral. Discovered structural damage on consumer's side of pipe.	Performed CCTV inspection; advised consumer to contact private plumber for repair.	867518
10	6/15/2020	2720 Kinsey Ave	21223	Roots	Dry	N/A	0	Gray water observed at the rear of the property.	15	Relieved house connection choke with 30 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	867595
11	6/16/2020	3526 Old Frederick Rd	21229	Rags, Trash	Dry	N/A	0	Gray water and paper observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	867965
12	6/17/2020	1248 N Gay St	21213	Rags, Trash	Dry	N/A	0	Gray water observed at the front of the property.	1	Relieved house connection choke with 15 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	868008
13	6/21/2020	6507 Pebble Brooke Rd	21209	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	868545
14	6/23/2020	2203 Presbury St	21216	Rags	Wet	N/A	0	Gray water observed around the cleanout at the front of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	868787
15	6/23/2020	1801 N Payson St	21217	Rags, Roots	Wet	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	868800
16	6/23/2020	Queensberry Ave & W Garrison Ave - SSO Site #139	21215	Rain	Wet	Jones Falls	45	Structured overflow discharging to a nearby storm drain.	7,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
17	6/23/2020	W Cold Spring Ln & Ayrdale Ave - SSO Site #138	21215	Rain	Wet	Gwynns Falls	65	Structure monitored by metering equipment in the pipe. Not visually observed.	25,000	SSO structure; not applicable.	The SSO structure will be closed upon completion of necessary capital project.	
18	6/23/2020	1000 Walker Ave	21239	Structural	Wet	Chinquapin Run	60	Gray water escaping multiple manholes due to pump failure and entering nearby waterway.	1,200	Bypass hose was repaired, stopping the overflow.	DPW informed contractor to take all measures to prevent this overflow from occurring again.	
19	6/25/2020	4302 Maine Ave	21207	Rags, Roots	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 75 ft of electric cable.	Performed CCTV inspection; confirmed lateral is clear.	869316
20	6/25/2020	4403 Liberty Heights Ave	21207	Rags, Roots, Grease	Wet	N/A	0	Gray water observed around the cleanout at the rear of the property.	1	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear.	869321
21	6/26/2020	624 S Monroe St - (Private)	21223	Structural	Dry	N/A	0	Gray water observed at the rear of the property.	1	Ran 3 ft of electric cable through lateral. Discovered structural damage on consumer's side of pipe.	Performed CCTV inspection; advised consumer to contact private plumber for repair.	869482

SSO Notification List

June 2020

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	6/26/2020	1915 Annapolis Rd	21230	Rags, Roots, Trash, Sand, Gravel, Rocks	Dry	Gwynns Falls	4097	Gray water escaping the manhole in the street.	12,291	Relieved mainline choke with 100 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	869540
23	6/27/2020	539 Bloom St	21217	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	1	Relieved house connection choke with 35 ft of electric cable.	Confirmed lateral is clear; CCTV inspection will be performed.	869601
24	6/28/2020	12 N Bentalou St	21223	Rags, Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	2	Ran 5 ft of electric cable through the lateral to remove blockage.	Left notice for the consumer to replace older-style trap.	869635
25	6/29/2020	1835 Bolton St	21217	Rags	Dry	N/A	0	Gray water observed at the rear of the property.	2	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral and mainline are clear; CCTV inspection will be performed.	869717
				# WWO	9			TOTAL	45,539	UNDER 100 GALLONS	18	