

SSO Notification List

November 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	11/1/2019	1901 Falls Rd	21218	Rain	Wet	Jones Falls	122	Heavy gray water escaping the manhole.	6,100	Overflow subsided following heavy rain event.	Location is equipped with an Event Notification System meter.	799387
2	11/1/2019	1731 E Chase St	21213	Rain, Trash	Wet	Harbor	55	Manhole surcharging due to heavy rain.	130,000	Flow returned to normal following heavy rain event. Traffic pattern set up.	Location is equipped with an Event Notification System meter.	799392
3	11/1/2019	Deepdene Rd & Edgevale Rd	21210	Rags, Roots, Trash	Wet	N/A	171	Gray water escaping the manhole.	171	Relieved 8" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	800123
4	11/2/2019	3010 Presbury St	21216	Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout at the front of the property.	3	Relieved house connection choke with 45 ft of electric cable.	CCTV inspection will be performed.	800226
5	11/2/2019	100 W Barre St	21201	Grease, Trash	Wet	N/A	0	Gray water and paper observed around the cleanout.	2	Relieved house connection choke with 60 ft of electric cable.	Confirmed lateral is clear.	800244
6	11/3/2019	3824 West Bay Ave	21225	Rags, Trash	Wet	N/A	108	Gray water escaping the manhole in the street.	2,160	Relieved 8" mainline choke with 200 ft of pressure hose.	Confirmed line is clear; CCTV inspection will be performed.	800267
7	11/5/2019	121 Kane St	21224	Unknown	Dry	Herring Run	13070	Gray water escaping from the manhole.	326,750	Set up bypass pumping to abate the overflow. Investigation has been ongoing to determine the cause of backup.	Long-term solution will be explored and implemented.	801955
8	11/6/2019	1312 Homewood Ave	21202	Rags, Roots	Dry	N/A	0	Gray water observed at the rear of the property.	3	Relieved house connection choke with 45 ft of electric cable.	Confirmed lateral is clear.	802388
9	11/7/2019	4722 York Rd	21212	Rags, Trash	Dry	Tiffany Run	176	Sewer choke causing subsurface overflow into storm drain.	88	Relieved mainline choke with 25 ft of pressure hose.	Confirmed line is clear via dye test.	802674
10	11/8/2019	Cylburn Ave & Greenspring Ave	21209	Rags, Roots	Dry	N/A	185	Gray water escaping the manhole in the street.	370	Relieved 10" mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear.	803156
11	11/8/2019	3826 West Bay Ave	21225	Rags, Grease, Trash	Dry	N/A	140	Gray water escaping the manhole.	280	Relieved mainline choke with 50 ft of pressure hose.	Confirmed mainline is clear.	803261
12	11/9/2019	5800 Reisterstown Rd	21215	Rags	Dry	N/A	60	Gray water escaping the cleanout at the front of the property.	30	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral and mainline are clear.	803508
13	11/12/2019	1802 Guilford Ave	21202	Trash	Dry	N/A	0	Gray water and paper observed around the cleanout at the rear of the property.	5	Relieved house connection choke with 30 ft of electric cable.	Confirmed lateral is clear.	804025
14	11/18/2019	2618 Huron St	21230	Structural, Unknown	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	7	Flushed and cleaned 8" mainline. Choke remained, therefore bypass pumping was set up.	CCTV inspection will be performed to determine cause of choke or potential structural damage.	806478
15	11/19/2019	3303 Abell Ave	21218	Rags	Dry	N/A	0	Gray water observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 15 ft of electric cable.	Performed CCTV inspection; confirmed lateral and mainline are clear.	807040
16	11/19/2019	1628 Braddish Ave	21216	Rags, Roots	Dry	N/A	0	Gray water and paper observed around the cleanout.	3	Relieved house connection choke with 60 ft of electric cable.	Performed CCTV inspection; confirmed mainline and lateral are clear.	807122
17	11/21/2019	500 North Point Rd	21224	Structural	Dry	Herring Run	5640	Water escaping the force main due to ARV malfunction.	564	Removed air release valve for repair. Gate valve has been shut down to isolate flow.	Air release valve will be restored to resume regular operation.	807977
18	11/22/2019	264 S Loudon Ave	21229	Rags, Roots, Trash	Dry	N/A	0	Gray water and debris observed around the cleanout at the rear of the property.	2	Relieved house connection choke with 90 ft of electric cable.	Performed CCTV inspection; flushed and cleaned the mainline.	808661
19	11/25/2019	3605 Woodbine Ave	21207	Structural	Wet	N/A	0	Gray water observed around at the rear of the property.	3	Ran 4 ft of electric cable in house connection.	Left notice to have plumber inspect consumer's side of the pipe and install cleanout. Confirmed mainline is clear.	809366

SSO Notification List

November 2019

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
20	11/25/2019	2701 Spelman Rd	21225	Rags, Grease, Trash	Wet	N/A	0	Gray water observed around the manhole in the street.	2	Relieved mainline choke with 200 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	809292
21	11/26/2019	453 Brunswick St	21223	Rags, Grease, Trash	Wet	N/A	213	Gray water escaping the manhole.	213	Relieved 8" mainline choke with 375 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	809594
22	11/27/2019	739 W Pratt St	21201	Rags, Grease, Trash	Wet	Harbor	76	Heavy gray water escaping the manhole in the street.	1,140	Relieved mainline choke with 500 ft of pressure hose.	Confirmed mainline is clear; performed CCTV inspection.	810080
23	11/27/2019	2514 Hamilton Ave	21214	Rags	Wet	N/A	131	Gray water escaping the cleanout at the front of the property.	7	Relieved house connection choke with 30 ft of electric cable.	Performed lateral CCTV inspection; confirmed line is clear. Advised consumer to install cleanout cap.	810225
24	11/28/2019	3700 Tudor Arms Ave	21211	Rags, Grease, Trash, Sand, Gravel, Rocks	Dry	N/A	1274	Heavy gray water escaping the manhole in the woods.	159,250	Relieved 12" mainline choke with 75 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	810280
25	11/29/2019	4123 Roland Ave	21211	Rags, Trash	Dry	N/A	0	Gray water observed around the manhole at the rear of the property.	3	Relieved mainline choke with 300 ft of pressure hose.	Confirmed mainline is clear; CCTV inspection will be performed.	810492
				# WWO	11			TOTAL	627,158	UNDER 100 GALLONS	14	