

SSO Notification List

April 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
1	4/1/2015	1715 Lancaster St	21231	Roots	DWO	Inner Harbor	5	Grey water, paper debris	10	Drain cleaning machine relieved the house connection choke	TV'd later connection	249233
2	4/1/2015	1212 Seminole Ave	21229	Rags, Trash, Sand, Gravel, Rocks, Pipe Break	DWO	N/A	431	Heavy gray water	2,155	Construction made repair to sewer main	CCTV	249291
3	4/1/2015	3300 Clipper Mill Rd	21211	Grease	DWO	Jones Falls	20	Sewage from manhole into storm then into stream. Saw discharging into stream. By the time I got to the stream it stopped. This is a reoccurring problem.	1,500	Overflow was abated, flow stopped without intervention	Follow up investigation at this location	249297
4	4/1/2015	1904 W Baltimore St	21223	Rags	DWO	N/A	Not Witnessed	Rags and evidence in alley	Evidence of Overflow	Used electric machine to relieve choke	CCTV	249324
5	4/2/2015	223 Woodlawn Rd	21210	Rags	DWO	N/A	Not Witnessed	Paper and evidence of an overflow	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	249434
6	4/3/2015	2716 Sethlow Rd	21225	Unknown	WWO	N/A	1,694	Gray water & Toilet paper	8,470	Unable to make contact with manager, bypassed locked gate and relieved choke	CCTV	249452
7	4/3/2015	429 Westgate Rd	21229	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence of overflow around house connection	Evidence of Overflow	Relieved house connection choke with 60' of electric machine	CCTV	249529
8	4/3/2015	1804 Bolton St	21217	Rags	WWO	N/A	Not Witnessed	Gray water & debris	Evidence of Overflow	Ran 75' of electric machine to relieve choke	CCTV	249491
9	4/3/2015	1013 Darley Ave	21218	Rags	WWO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	249568
10	4/6/2015	3200 Carlisle Ave	21216	Grease	DWO	N/A	Not Witnessed	Overflowing into storm then flowing into stream at Hanlon Park	Evidence of Overflow	Relieved mainline choke with press truck 275 ft of 8"	CCTV	249709
11	4/6/2015	1126 Shields Pl	21201	Rags	DWO	N/A	Not Witnessed	Evidence of spillage around the clean out	Evidence of Overflow	Used electric machine to try and relieve choke	CCTV	249760
12	4/6/2015	2501 Maryland Ave	21218	Rags	DWO	N/A	Not Witnessed	Heavy gray water	Evidence of Overflow	Relieved house connection choke, used 45 ft of 6"	CCTV	249765
13	4/7/2015	4221 Belvieu Ave	21215	Rags	WWO	N/A	Not Witnessed	Rags and evidence around clean out	Evidence of Overflow	Used electric machine to relieve choke	CCTV	249993
14	4/8/2015	4215 Belmar Ave	21206	Rags	WWO	N/A	Not Witnessed	Rags and evidence around clean out	Evidence of Overflow	Used electric machine to relieve house connection choke	CCTV	250187
15	4/8/2015	Orville Ave and E Federal St	21205	Pipe Break	WWO	Armistead Creek	1,775	Gray colored water flowing	34,940	Contractor called in to stop overflow	Valves were shut off	250178
16	4/8/2015	2446 E 32nd St	21213	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Paper and evidence around the clean out	Evidence of Overflow	Used electric machine to help relieve house connection choke	CCTV	250064
17	4/9/2015	2806 Roselawn Ave	21214	Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence of overflow around the clean out	Evidence of Overflow	Relieved choke with electric machine	CCTV	250247
18	4/9/2015	1008 Billie Holiday Ct	21205	Rags, Trash, Sand, Gravel, Rocks	WWO	N/A	Not Witnessed	Evidence, paper and rags around clean out	Evidence of Overflow	Used pressure hose to relieve choke	CCTV	250367
19	4/11/2015	200 Ballou Ct	21231	Grease	WWO	N/A	Not Witnessed	Grease and rags causing mainline choke	Evidence of Overflow	Relieved mainline choke with pressure truck	CCTV	250583
20	4/13/2015	2027 Dukeland St	21216	Roots	DWO	N/A	Not Witnessed	Toilet paper and evidence around clean out	Evidence of Overflow	Relieved choke with 45' electric machine	CCTV	250743
21	4/13/2015	2605 Dulany St	21223	Rags	DWO	N/A	Not Witnessed	Rags and evidence of an overflow around clean out	Evidence of Overflow	Used electric machine to help relieve choke	CCTV	250845

SSO Notification List

April 2015

Serial No.	Date of Occurrence	Location	Zip Code	Reason	Dry or Wet-Weather Overflow?	Stream Affected	Duration (Hrs:Min)	Description of Discharge	Est. Quantity of Discharge (gallons)	Measures taken to Minimize Discharge	Preventive Action to Stop Recurrence	Work Order #
22	4/13/2015	208 Stratford Rd	21218	Other	DWO	N/A	Not Witnessed	Sidewalk wet, evidence of spillage from sump pump	Evidence of Overflow	Used sewer jet	CCTV	250855
23	4/14/2015	429 Westgate Rd	21229	Roots, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Gray water & debris	Evidence of Overflow	Relieved choke with 45' of electric machine	CCTV	250853
24	4/14/2015	3130 Guilford Ave	21218	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Toilet paper, evidence and muck around clean out	Evidence of Overflow	Ran 45 ft of electric machine to relieve choke & turned over to sewer rodder to cut roots	CCTV the mainline	250886
25	4/15/2015	6216 Pinehurst Rd	21212	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Sewer water and evidence of an overflow at this location	Evidence of Overflow	Relieved the house connection choke with electric machine	CCTV	251018
26	4/15/2015	4105 Raspe Ave	21206	Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Paper and evidence around clean out	Evidence of Overflow	Relieved choke with electric machine	CCTV	251052
27	4/15/2015	3300 Clipper Mill Rd	21211	Other	WVO	N/A	Not Witnessed	Evidence of sewage around manhole	Evidence of Overflow	Removed the hose from the mainline	Hose was removed, no longer blocking line	251154
28	4/15/2015	1822 Penrose Ave	21223	Rags	WVO	N/A	Not Witnessed	Rags and evidence around the clean out	Evidence of Overflow	Used electric machine to help relieve choke	CCTV	251187
29	4/16/2015	2467 Harriet Ave	21230	Rags	WVO	N/A	Not Witnessed	Toilet paper and other evidence around the cleanout	Evidence of Overflow	Relieved choke with 32' of electric machine	CCTV	251290
30	4/16/2015	4000 Groveland Ave	21215	Rags, Roots	WVO	N/A	Not Witnessed	Wet area around clean out, evidence of an overflow	Evidence of Overflow	Used electric machine to relieve the choke	CCTV	251353
31	4/17/2015	6803 Harford Rd	21234	Rags, Grease	WVO	N/A	Not Witnessed	Toilet paper and evidence of spillage	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	251446
32	4/17/2015	4107 The Alameda	21218	Rags, Roots	WVO	N/A	Not Witnessed	Rags and evidence of overflow around clean out	Evidence of Overflow	Used electric machine to help relieve the choke	CCTV	251532
33	4/18/2015	Braddish Ave & Edmondson Ave	21216	Rags, Grease	DWO	N/A	721	Gray water	2,163	Relieved mainline choke with pressure truck, 60 ft of 8"	CCTV	251553
34	4/18/2015	3204 Juneau Pl	21214	Pipe Break	WVO	N/A	Not Witnessed	Gray water and evidence near the clean out	Evidence of Overflow	Ran 8' of electric machine to help relieve choke	Turn over M.T.P	251587
35	4/19/2015	1800 Ruxton Ave	21216	Roots	WVO	N/A	Not Witnessed	Toilet paper and muck around the house connection	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	251613
36	4/19/2015	2819 Goodwood Rd	21214	Roots	WVO	N/A	Not Witnessed	Toilet paper and other evidence around the clean out	Evidence of Overflow	Relieved house connection choke with 30' of electric machine	CCTV	251656
37	4/20/2015	4403 Frederick Ave	21229	Grease	WVO	N/A	Not Witnessed	Gray water and evidence around manhole	Evidence of Overflow	Relieved mainline choke with pressure truck, 300 ft of 8"	CCTV	251745
38	4/20/2015	1801 E Eager St	21205	Rags, Trash, Sand, Gravel, Rocks	WVO	N/A	Not Witnessed	Not discharging at this time, evidence around manhole	Evidence of Overflow	Relieved mainline choke with 350 ft of pressure hose, mainline clear	CCTV	251747
39	4/20/2015	1500 N Charles St	21202	Rain, Infiltration/Inflow	WVO	Jones Falls	200	Muck & debris	10,000	Secured 30" sanitary M/H cover. Pressure truck will wash area in AM	Monitor during heavy Rain storm	251782
40	4/21/2015	2904 Glenmore Ave	21214	Rags	WVO	N/A	Not Witnessed	Wet around manhole, evidence of an overflow	Evidence of Overflow	Used sewer jet to clean around manhole	CCTV	
41	4/21/2015	5511 Elderon Ave	21215	Rags	WVO	N/A	Not Witnessed	Paper and rags	Evidence of Overflow	Used electric machine to help relieve choke	CCTV	251881
42	4/22/2015	1939 Falls Rd	21217	Rags, Grease	WVO	N/A	Not Witnessed	Manhole showed evidence of overflow due to heavy rain	Evidence of Overflow	Relieved mainline choke	CCTV	252115
43	4/22/2015	5235 Linden Heights Ave	21215	Roots	WVO	N/A	Not Witnessed	Evidence of sewer water and toilet paper around clean out	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	252090
44	4/22/2015	2501 Maryland Ave	21218	Rags, Grease	WVO	N/A	Not Witnessed	Toilet paper and murky water around house connection	Evidence of Overflow	Relieved house connection choke with electric machine	CCTV	25129

